



F: ;E ? ; J 7D F3B ? GEF 47 ;@EF3 >>76 4K 3 > ;57@E76 B>G? 47D ;@ 355AD63@571 ;F: >A 53>D79G>3F;A @Ež

FZ[eA fhW] fSb [e\_ S` gXSurgdW fa efS` VSd/ 3E!@LE %> #\*ž

? 3J AB7D3F:@9 BD7EEGD7, [XXX] TSd/ " " ] BSfi  
D75A ? ? 7@676 AB7D3F;A @ BD7EEGD7, [XXX] #Z ž TSd/#' " ž " " ] BSfi  
? 3J : AF I 3F7D F7? B7D3FGD7, [XXX] (' »5  
D75A ? ? 7@676 : AF I 3F7D F7? B7D3FGD7, [XXX] »5

I ZWM SFVbdVegdWYUWVe' " " ] BSI SbdVegdWdWgUf` Y VVhUW[e dWg[dW fa TW] efS^Wž  
@afWfZSfi SfVbdVegdWahVd [YZf US` dVSLZ #' " . aXfZWSkf\_ WbdVegdWž

**Note:** ; efS^Sf[a` aXSWsfadeUa` fS[ [ Y Xai` dVg^Sfadž  
Gba` dV] efS^Sf[a` f ZWSVsfadežagV TWf [YZfW VV i [fZ S` SWsfad] VV fa bdWVW f  
dV\_ ahS^Tk ZS` Vž

**Note:** 5WIS\_ [U5SfdqVYVž ŽI SctS` fk US\_ ei [^^ afTWZa` agdW i ZVdWfZWVMS\_ [U  
USfdqVYVWZSe\_ S^g` Uf[a` W VgWfa fZWbdWV UW] fZVW SFVdVegbb` aX  
‡ 5abbVdVfgTWb[VW] eS` VI V[cf adefa` Vž  
‡ FZdVSV fSbW  
‡ AfZVdaTWVfe` af` ad\_ S^k bdWVW f [ bafST^Mi SFVdVegbb` Vž  
6a` af dV\_ ahWfZWUSfdqVYVWcb\_ fZWTaVk Se [f ZSe TWV bdVegdWfVefW S` V  
f [YZfW VV fa S ebWU]XU factgVž

4WadVsfW bf[ Y S` ki ad] [ ha`h[ Y\_ S] ei SFVdVegbb` k f Vž W egdWfZW i SFVdVegbb` [e  
eZgf aXž

Efab hS`hVbdWVST k i [fZ X fVdVef\_ gef TWgeW i ZW [ efS^f Y kagda fhW] \_ [j VdVfa S^ai  
[ea Sf[a` / af egbb` VV i [fZ \_ [j VdVfS]gdVfa Va ea i ZVdWdWg[dW i [^^ha[V i SctS` fkž

FZ[e\_ [j VdVfSb [e S`dVSVk bdVžSeV\_ T VV S` V fVdVWž 6a` af V[eSeV\_ T VV Se fZ[e\_ Sk ha[V  
fZWi SctS` fkž

FZ[e\_ [j VdVfSb \_ gef TW] efS^W [ SUad/S` UM [fZ fZVW] efcgUf[a` ež

Oliveri Solutions Pty Ltd ABN 12 007 551 886  
51 Naweena Rd, Regency Park SA 5010 P 08 8348 6444 E sales@oliveri.com.au

# Essente



## Stainless Steel Right Angle Mixer SS2540

### CARE & MAINTENANCE

Unscrew and clean the spout aerator periodically - especially if you notice a drop in water pressure. The finish on your Oliveri mixer tap will resist stains and dirt build up.

Clean with a soft cloth and warm soapy water as necessary - rinse and dry after cleaning. Avoid using abrasive or acid based cleaning products.

### WARRANTY

This mixer tap is warranted to be free from manufacturing defects for a period of 10 Years: Cartridge: 10 years replacement parts, 1 year labour; Body including handle: 7 years replacement parts and labour; Finish: 5 years replacement parts, 1 year labour, when used in a domestic situation.

Where a genuine manufacturing defect arises within the warranty period Oliveri will, at its election, repair the defect or replace the product subject to the terms contained in the full warranty information available at <https://oliveri.com.au/service-and-warranty>.

**This warranty does not cover against normal wear and will be voided if the product is misused or not installed in accordance with these instructions.** Note: Fitting spout-attached devices, including water filters, to this mixer will void warranty.

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.

### SERVICE

**If the problem represents a danger, or damage to property may occur, immediately shut off the water supply.** If the mixer tap requires servicing, please contact your plumber (preferably the one who installed it). Most problems occur due to contaminated supply lines or water pressure exceeding 500kPa. Unscrew and clean the spout aerator periodically - especially if you notice a drop in water pressure.

If the plumber / installer is satisfied that the problem is not due to poor installation, contact Oliveri's nominated Warranty Service Agent for assistance on:

Ph: (08) 8348 6444 (choose the after sales service and warranty option)  
Email: [warranty@oliveri.com.au](mailto:warranty@oliveri.com.au)  
For full warranty information visit: <https://oliveri.com.au/service-and-warranty>

**If a warranty service call finds that the product does not have a genuine manufacturing fault, our Warranty Service Agent reserves the right to pass on any call-out fee to the householder.**

